

Mercury Super Hipster  
HPT-1001  
30-2001-ME

<b>Component ID</b>	<b>Component Description</b>	<b>Qty Needed</b>
10-0004	Lid Rivet	2.00
10-0008-B	Dome Filter With Bag Support	1.00
10-0014	Motor Screws	4.00
10-0015	_ Flat Washer	4.00
10-0017	Deflector Screws	1.00
10-0024-B	1 _" Vacuum Hose	4.00
10-0025	On/Off Switch	1.00
10-0028	50' Electrical Cord	1.00
10-0032	14" Scalloped Floor Tool	1.00
10-0033	17" Crevice Tool	1.00
10-0037	3" Round Dust Brush	1.00
10-0050-B	Vac Rivet	6.00
10-0055-L	Hipster Waist Belt Screw	3.00
10-0217	Hipster Waist Belt Washer	3.00
10-0195	Swivel Cuff	1.00
10-0197	6 qt. Paper Bags/10 Pack	0.10
10-0199	Vacuum Motor Gasket w/PSA	1.00
10-0202	Grommet For Hipster Lid	1.00
10-0216	Allen Head Screw For Back Pack	4.00
10-0225-ME	Hipster Body	1.00
10-0013	Super Motor	1.00
10-0420	Hipster Shipping Box	1.00
10-0421	Hipster Waist Belt	1.00
10-0003	Lid Latch	4.00
10-0165	Copper Ring	1.00
10-0425	Cloth Bag Material	0.50
10-0452	Grommet for Hipster Bag	1.00
10-0223-A	2 Piece Head For Wand	1.00
10-1024	Motor Mount Plate for Spotter	1.00
10-0353	Reticulated Foam For Hipster	1.00
10-0031	5" Upholstery Tool	1.00
90-1024	Washer for AirMover & Hipster	6.00
10-0045	2 Pc 2 Bend Button Lock Wand	1.00
10-0027	Pigtail Strain Relief Spotter	1.00
10-0027-A	Strain Relief Nut For Spotter	1.00
10-0026	17" Power Cord For Back Pack	1.00