

**2 Gallon Spotter  
50-2000**

<b>Component ID</b>	<b>Component Description</b>	<b>Qty Needed</b>
10-0499-A	Tee Jet for hand tool 4Spot	1.00
10-0499	Nut for jet on hand tool 4Spot	1.00
10-0500	4" Upholstery Tool w/Internal	1.00
10-0403	1/8 Brass Female Coupler	1.00
50-1007	7' Black Hose for Spotter	1.00
10-0475	Solution Hose for Spotter	1.00
10-0474	1/8" QD Female for Spotter	1.00
10-0463	Black Slip Hose Cuff 4 Spotter	2.00
10-0027-A	Strain Relief Nut For Spotter	1.00
10-0027	Pigtail Strain Relief Spotter	1.00
10-0448	20 Ft. Spotter/Airmover Cord	1.00
10-0015	_ Flat Washer	6.00
10-0022	Shoulder & Waist Belt Screw	4.00
10-0025	On/Off Switch	1.00
10-0050-B	Vac Rivet	12.00
10-0300	Pump For Spotter	1.00
10-0301	L Bracket For Spotter	1.00
10-0304	Spotter Cap And Float Assembly	1.00
10-0447	P-2 Spotter Motor	1.00
10-0380	10-32 x 3/8" Screw	2.00
10-0383	6/32 x _ Phil Pan Blk Screw	2.00
10-0386	Stamped Motor Screen	1.00
10-0393	Spotter Shipping Box	1.00
10-0402	1/8" QD Male	1.00
10-0403	1/8 Brass Female Coupler	2.00
10-0405	1 _ PVC SCH40 Slip Thread	1.00
10-0406	Nylon Barb 90 1/8 NPT _	2.00
10-0407	Barb Nylon Straight 1/8 NPT X	1.00
10-0434	Threaded Hose for Spotter	1.00
10-0435	Oetiker Clamp	2.00
10-0467	Switch Panel 2gal. Spot Xtract	1.00
10-0470	2 Gallon Spotter Body	1.00
10-0473	Bolt For 2 Gal. Spotter	3.00
10-1030	Spotter Motor Gasket	1.00

**2 Gallon Spotter  
50-2000**

10-0483	Bottom Base Plate for 2 Gal.	1.00
---------	------------------------------	------