

Component ID	Component Description	Qty Needed
10-0027-A	Strain Relief Nut For Spotter	1.00
10-0027	Pigtail Strain Relief Spotter	1.00
10-0448	20 Ft. Spotter/Airmover Cord	1.00
10-0499-A	Tee Jet for hand tool 4Spot	1.00
10-0499	Nut for jet on hand tool 4Spot	1.00
10-0501	4" Stainless Upholstery Tool	1.00
10-0403	1/8 Brass Female Coupler	1.00
50-1007	7' Black Hose for Spotter	1.00
10-0475	Solution Hose for Spotter	1.00
10-0474	1/8" QD Female for Spotter	1.00
10-0463	Black Slip Hose Cuff 4 Spotter	2.00
10-0014	Motor Screws	2.00
10-0015	Flat Washer	2.00
10-0017	Deflector Screws	1.00
10-0380	10-32 x 3/8" Screw	6.00
10-0025	On/Off Switch	1.00
10-0050-B	Vac Rivet	6.00
10-0216	Allen Head Screw For Back Pack	4.00
10-0300	Pump For Spotter	1.00
10-0301	L Bracket For Spotter	1.00
10-0304	Spotter Cap And Float Assembly	1.00
10-0350-S	Sandia 3 Gal. Spot Xtract Body	1.00
10-0366	Super Spotter Motor	1.00
10-0383	6/32 x Phil Pan Blk Screw	4.00
10-0384	.125 Thick Nylon Washer	4.00
10-0385	.06 Thick Nylon Washer	4.00
10-0386	Stamped Motor Screen	1.00
10-0387	5/16 x 1" Socket Head Bolt	2.00
10-0393	Spotter Shipping Box	1.00
10-0400-D	Latch for Sniper	1.00
10-0400-C	Keeper Latch for Sniper	1.00
10-0402	1/8" QD Male	1.00
10-0405	1" PVC SCH40 Slip Thread	1.00
10-0406	Nylon Barb 90 1/8 NPT	3.00
10-0407	Barb Nylon Straight 1/8 NPT X	2.00
10-0412	C Channel For Spotter	2.00
10-0414	Rivet For Spotter Handle	4.00
10-0416-A	ABS Stand Pipe Black 1"	1.00
10-0434	Threaded Hose for Spotter	3.00
10-0435	Oetiker Clamp	4.00
10-1024	Motor Mount Plate for Spotter	1.00
10-1025	Back Switch Plate for 3 gal.	1.00
10-1028	Bottom Base Plate for Spotter	1.00
10-1030	Spotter Motor Gasket	1.00
10-0303	Roller Blade Wheel	2.00